

Cluster-31, Unit no. 83 to 86

Civil substructure works foundation completed.

Ground floor slab completed.

1st floor slab complete.

Brick work is completed.

Roof slab is completed.

Plaster work is in done.

Anti termite work completed.

Waterproofing work is done.

External paint is in completed.

Flooring work is in completed.

Finishing work is in completed.

External paint is in completed.

