

## **Cluster-29, Unit no.98 to 99**

Sub structure is completed.

Ground floor slab is completed.

Brick work is completed.

1st floor slab completed.

Roof slab is completed.

Internal Electrical work in completed.

Plaster work is completed.

Plumbing work is in completed.

Flooring work is in completed.

Finishing Work is in completed.

External paint is in completed.

