

Cluster-30, Unit no.93 to 97

Substructure work completed.

Ground floor slab completed.

1st floor slab completed.

Roof slab is completed.

Brick work is completed.

Internal Electrical work in completed.

Plaster work is completed.

Plumbing work is in completed.

Anti termite work completed.

Waterproofing completed.

Flooring work is in completed.(93 to 97)

Finishing work is in completed.

External paint is in completed.

