

## **Cluster-32, Unit no.79 to 82**

Civil substructure works foundation completed.

Ground floor slab completed.

First floor slab completed.

Brickwork work in completed.

Internal Electrical work in completed.

Mumty room slab completed.

Plastering work is done.

Internal Plumbing work in completed

Anti termite work completed

Flooring work is in completed.

Waterproofing is completed.

Finishing work is in completed.

External paint is in completed.

