

Cluster-33,Unit no. 60 to 62

Civil substructure works foundation completed.

Ground floor slab completed.

1st floor slab completed.

Brickwork work in completed.

Roof slab is completed.

Internal Electrical work in completed.

Plastering work is done.

Plumbing work is in completed.

Anti termite work completed.

Waterproofing is completed.

Flooring work is in completed.

Finishing work is on completed.

External paint is in completed.

