

Construction Update of Botanica-4th July,2025

PHASE-I

1.Cluster-03,Unitno.11 to15

- Civil substructure works complete.
- Ground floor slab completed.
- 1st floor slab completed.
- Roof slab completed
- Brickwork work completed
- Plastering work completed
- Internal Electrical Wiring work completed.
- Internal Plumbing work in completed.
- Water Proofing completed.
- Pop work is in completed.
- Anti termite work completed
- Flooring work is in completed.
- Finishing work is in completed.
- External paint is completed.

2.Cluster-4, Unitno.16 to 21

Civil substructure works foundation completed.

Ground floor slab completed.

- 1st floor slab completed.
- Brickwork completed.
- Roof slab is completed.
- Electrical work is in completed.
- Internal Plumbing completed.
- Plastering work is completed.
- Anti termite work completed.
- Waterproofing completed.
- Flooring work in completed.
- Finishing work is on completed.
- External paint is completed.

3.Cluster-15,Unitno.57to 59

- Civil substructure works foundation complete.
- Ground floor slab completed.
- 1st floor slab completed.
- Roof slab completed.
- Brickwork completed.
- Plastering work completed.
- Internal Electrical wiring work in completed.
- Internal Plumbing work in completed
- Waterproofing work completed.
- Pop work in completed.
- Flooring work in completed.
- Anti termite work completed.
- Finishing work is in completed.
- External paint is in completed.

4.Cluster-16,Unitno.34to37

- Civil sub-structure works completed.
- Civil super-structure works completed.
- Ground floor slab completed.
- 1st floor slab completed.
- Roof slab completed.
- Brickwork completed.
- Plastering work completed.
- Internal Plumbing work in completed.
- Internal Electrical Work is in completed.
- Water Proofing completed.
- Pop work in completed.
- Anti termite work completed.
- Flooring work in completed.
- Finishing work is on completed.
- External paint is in completed.

5.Cluster-17,Unitno.26 to 33

Civil substructure works foundation completed.

Ground floor slab completed.

Brickwork work is completed.

- 1st floor slab completed.
- Internal Electrical work in completed.
- Roof slab is completed.
- Plastering work is completed.
- Internal Plumbing work in completed.
- Anti termite work completed.
- Waterproofing work is in completed.
- Flooring work is in completed.
- Finishing work is on completed.
- External paint is in completed.

6.Cluster-19,Unitno.38to47

- Civilsub-structureworks foundation complete.
- Ground floor slab completed.
- Brickwork work is completed.
- First floor slab completed.
- Internal Electrical Wiring work in completed.
- Roof slab completed.
- Plastering work is completed.
- Internal Plumbing work in completed.
- Anti termite work completed.
- Waterproofing work is completed.
- Flooring work is in completed.
- Finishing work is on completed.
- External paint is in .

7.Cluster-20,Unitno.48to56

- Civilsubstructureworksfoundation complete.
- Ground floor slab completed.
- Brickwork work is completed.
- First floor slab completed.
- Internal Electrical Wiring work in completed.
- Roof slab completed.
- Plastering work is completed.
- Internal Plumbing work in completed.
- Pop work in completed.
- Anti termite work completed.
- Waterproofing is completed.
- Flooring work is in completed.
- Finishing work is on completed.
- External paint is in completed.

8.Cluster-21,Unitno.63 to 70

Civil substructure works foundation complete.

Ground floor slab completed.

- Brickwork work is completed.
- 1st floor slab completed.
- Roof slab is completed.
- Internal Electrical work in completed.
- Plastering work is completed.
- Internal Plumbing work in completed.
- Anti termite work completed.
- Waterproofing is completed.
- Flooring work is in completed.(63 to 70)
- Finishing work is on progress.
- External paint is completed.

9.Cluster-22,Unitno.71to78

- Civilsubstructureworksfoundation complete.

- Ground floor slab completed.
- 1st floor slab completed.
- Roof slab completed.
- Brickwork work is completed.
- Internal Electrical work is completed.
- Plastering work in completed.
- Internal Plumbing work in completed.
- Pop work in completed.
- Anti termite work completed.
- Waterproofing work is completed.
- Flooring work is in completed.(71 to 78)
- Finishing work in completed.(71,72,73,74,76,75,77,78)
- External paint is in completed.

10.Cluster-23,Unit no. 87 to 92

Civil substructure works foundation completed.

Ground floor slab completed.

- 1st floor slab completed.
- Roof slab completed.

Brickwork work is completed.(87 to 92)

Internal Electrical work in completed.

Plumbing work is in completed.

Plastering work is completed.

- Anti termite work completed.
- Waterproofing work is completed.
- Flooring work is in completed.(87 to 92)
- Finishing work is on completed.
- External paint is in completed.

11.Cluster-29, Unit no.98 to 99

Sub structure is completed.

Ground floor slab is completed.

Brick work is completed.

1st floor slabcompleted.

Roof slab is completed.

Internal Electrical work in completed.

Plaster work is completed.

Plumbing work is in completed.

- Flooring work is in completed.
- Finishing Work is in completed.
- External paint is in completed.

12.Cluster-30, Unit no.93 to 97

- Substructure work completed.

- Ground floor slab completed.

- 1st floor slab completed.

- Roof slab is completed.
- Brick work is completed.
- Internal Electrical work in completed.
- Plaster work is completed.
- Plumbing work is in completed.
- Anti termite work completed.
- Waterproofing completed.
- Flooring work is in completed.(93 to 97)
- Finishing work is in completed.
- External paint is in completed.

13.Cluster-31, Unit no. 83 to 86

Civil substructure works foundation completed.

Ground floor slab completed.

1st floor slab complete.

Brick work is completed.

Roof slab is completed.

Plaster work is in done.

- Anti termite work completed.
- Waterproofing work is done.
- External paint is in completed.
- Flooring work is in completed.
- Finishing work is in completed.
- External paint is in completed.

14.Cluster-32, Unit no.79 to 82

Civil substructure works foundation completed.

Ground floor slab completed.

First floor slab completed.

Brickwork work in completed.

- Internal Electrical work in completed.
- Mumty room slab completed.
- Plastering work is done.
- Internal Plumbing work in completed
- Anti termite work completed
- Flooring work is in completed.
- Waterproofing is completed.
- Finishing work is in completed.
- External paint is in completed.

15.Cluster-33,Unit no. 60 to 62

Civil substructure works foundation completed.

Ground floor slab completed.

- 1st floor slab completed.

Brickwork work in completed.

Roof slab is completed.

- Internal Electrical work in completed.

- Plastering work is done.
- Plumbing work is in completed.
- Anti termite work completed.
- Waterproofing is completed.
- Flooring work is in completed.
- Finishing work is on completed.
- External paint is in completed.

CLUB:

- Piling Completed.
- Excavation work in completed.
- Raft Completed.
- Retaining Wall completed.
- Ground floor slab completed .
- 1st floor slab is completed.
- Brick work is in progress.
- 2nd floor slab is completed.
- Plaster work is in progress.
- Roof slab is completed.
- POP work is in progress.
- Aluminium work is in progress.
- Fire work is in progress.
- Waterproofing work is in progress.

ROAD

- Flooring work of road is completed at cl-3&4 ,cl-17&19, cl-15&33, cl-20&21, 22&23,31&32,29&30.
- Landscape work is completed.