

Construction Update of
Botanica-9th October,2025
PHASE-I

1.Cluster-03,Unitno.11 to15

- ▮ Civil substructure works complete.
- ▮ Ground floor slab completed.
- ▮ 1st floor slab completed.
- ▮ Roof slab completed
- ▮ Brickwork work completed
- ▮ Plastering work completed
- ▮ Internal Electrical Wiring work completed.
- ▮ Internal Plumbing work in completed.
- ▮ Water Proofing completed.
- ▮ Pop work is in completed.
- ▮ Anti termite work completed
- ▮ Flooring work is in completed.
- ▮ Finishing work is in completed.
- ▮ External paint is completed.

2.Cluster-4, Unitno.16 to 21

- ▮ Civil substructure works foundation completed.
- ▮ Ground floor slab completed.
- ▮ 1st floor slab completed.
- ▮ Brickwork completed.
- ▮ Roof slab is completed.
- ▮ Electrical work is in completed.
- ▮ Internal Plumbing completed.
- ▮ Plastering work is completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing completed.
- ▮ Flooring work in completed.
- ▮ Finishing work is on completed.
- ▮ External paint is completed.

3.Cluster–15,Unitno.57to 59

- ▮ Civil sub structure works foundation complete.
- ▮ Ground floor slab completed.
- ▮ 1st floor slab completed.
- ▮ Roof slab completed.
- ▮ Brickwork completed.
- ▮ Plastering work completed.
- ▮ Internal Electrical wiring work in completed.
- ▮ Internal Plumbing work in completed
- ▮ Waterproofing work completed.
- ▮ Pop work in completed.
- ▮ Flooring work in completed.
- ▮ Anti termite work completed.
- ▮ Finishing work is in completed.
- ▮ External paint is in completed.

4.Cluster–16,Unitno.34to37

- Civilsub-structureworkscompleted.
- Civil super-structure works completed.
- Ground floor slab completed.
- 1stfloor slab completed.
- Roof slab completed.
- Brickwork completed.
- Plastering work completed.
- Internal Plumbing work in completed.
- Internal Electrical Work is in completed.
- Water Proofing completed.
- Pop work in completed.
- Anti termite work completed.
- Flooring work in completed.
- Finishing work is on completed.
- External paint is in completed.

5.Cluster–17,Unitno.26 to 33

- ▮ Civil substructure works foundation completed.
- ▮ Ground floor slab completed.
- ▮ Brickwork work is completed.

- ▮ 1st floor slab completed.
- ▮ Internal Electrical work in completed.
- ▮ Roof slab is completed.
- ▮ Plastering work is completed.
- ▮ Internal Plumbing work in completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing work is in completed.
- ▮ Flooring work is in completed.
- ▮ Finishing work is on completed.
- ▮ External paint is in completed.

6.Cluster–19,Unitno.38to47

- ▮ Civilsub-structureworks foundation complete.
- ▮ Ground floor slab completed.
- ▮ Brickwork work is completed.
- ▮ First floor slab completed.
- ▮ Internal Electrical Wiring work in completed.
- ▮ Roof slab completed.
- ▮ Plastering work is completed.
- ▮ Internal Plumbing work in completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing work is completed.
- ▮ Flooring work is in completed.
- ▮ Finishing work is on completed.
- ▮ External paint is in .

7.Cluster–20,Unitno.48to56

- ▮ Civilsubstructureworksfoundation complete.
- ▮ Ground floor slab completed.
- ▮ Brickwork work is completed.
- ▮ First floor slab completed.
- ▮ Internal Electrical Wiring work in completed.
- ▮ Roof slab completed.
- ▮ Plastering work is completed.
- ▮ Internal Plumbing work in completed.
- ▮ Pop work in completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing is completed.
- ▮ Flooring work is in completed.
- ▮ Finishing work is on completed.
- ▮ External paint is in completed.

8.Cluster-21,Unitno.63 to 70

- ▮ Civil substructure works foundation complete.
- ▮ Ground floor slab completed.
- ▮ Brickwork work is completed.
- ▮ 1st floor slab completed.
- ▮ Roof slab is completed.
- ▮ Internal Electrical work in completed.
- ▮ Plastering work is completed.
- ▮ Internal Plumbing work in completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing is completed.
- ▮ Flooring work is in completed.(63 to 70)
- ▮ Finishing work is on progress.
- ▮ External paint is completed.

9.Cluster-22,Unitno.71to78

- ▮ Civilsubstructureworksfoundation complete.
- ▮ Ground floor slab completed.
- ▮ 1st floor slab completed.
- ▮ Roof slab completed.
- ▮ Brickwork work is completed.
- ▮ Internal Electrical work is completed.
- ▮ Plastering work in completed.
- ▮ Internal Plumbing work in completed.
- ▮ Pop work in completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing work is completed.
- ▮ Flooring work is in completed.(71 to 78)
- ▮ Finishing work in completed.(71,72,73,74,76,75,77,78)
- ▮ External paint is in completed.

10.Cluster-23,Unit no. 87 to 92

- ▮ Civil substructure works foundation completed.
- ▮ Ground floor slab completed.
- ▮ 1st floor slab completed.
- ▮ Roof slab completed.
- ▮ Brickwork work is completed.(87 to 92)
- ▮ Internal Electrical work in completed.

- ▮ Plumbing work is in completed.
- ▮ Plastering work is completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing work is completed.
- ▮ Flooring work is in completed.(87 to 92)
- ▮ Finishing work is on completed.
- ▮ External paint is in completed.

11.Cluster-29, Unit no.98 to 99

- ▮ Sub structure is completed.
- ▮ Ground floor slab is completed.
- ▮ Brick work is completed.
- ▮ 1st floor slabcompleted.
- ▮ Roof slab is completed.
- ▮ Internal Electrical work in completed.
- ▮ Plaster work is completed.
- ▮ Plumbing work is in completed.
- ▮ Flooring work is in completed.
- ▮ Finishing Work is in completed.
- ▮ External paint is in completed.

12.Cluster-30, Unit no.93 to 97

- ▮ Substructure work completed.
- ▮ Ground floor slab completed.
- ▮ 1st floor slab completed.
- ▮ Roof slab is completed.
- ▮ Brick work is completed.
- ▮ Internal Electrical work in completed.
- ▮ Plaster work is completed.
- ▮ Plumbing work is in completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing completed.
- ▮ Flooring work is in completed.(93 to 97)
- ▮ Finishing work is in completed.
- ▮ External paint is in completed.

13.Cluster-31, Unit no. 83 to 86

- ▮ Civil substructure works foundation completed.
- ▮ Ground floor slab completed.

- ▮ 1st floor slab complete.
- ▮ Brick work is completed.
- ▮ Roof slab is completed.
- ▮ Plaster work is in done.
- ▮ Anti termite work completed.
- ▮ Waterproofing work is done.
- ▮ External paint is in completed.
- ▮ Flooring work is in completed.
- ▮ Finishing work is in completed.
- ▮ External paint is in completed.

14.Cluster–32, Unit no.79 to 82

- ▮ Civil substructure works foundation completed.
- ▮ Ground floor slab completed.
- ▮ First floor slab completed.
- ▮ Brickwork work in completed.
- ▮ Internal Electrical work in completed.
- ▮ Mumty room slab completed.
- ▮ Plastering work is done.
- ▮ Internal Plumbing work in completed
- ▮ Anti termite work completed
- ▮ Flooring work is in completed.
- ▮ Waterproofing is completed.
- ▮ Finishing work is in completed.
- ▮ External paint is in completed.

15.Cluster–33,Unit no. 60 to 62

- ▮ Civil substructure works foundation completed.
- ▮ Ground floor slab completed.
- ▮ 1st floor slab completed.
- ▮ Brickwork work in completed.
- ▮ Roof slab is completed.
- ▮ Internal Electrical work in completed.
- ▮ Plastering work is done.
- ▮ Plumbing work is in completed.
- ▮ Anti termite work completed.
- ▮ Waterproofing is completed.
- ▮ Flooring work is in completed.
- ▮ Finishing work is on completed.
- ▮ External paint is in completed.

CLUB:

- ▮ Piling Completed.
- ▮ Excavation work in completed.
- ▮ Raft Completed.
- ▮ Retaining Wall completed.
- ▮ Ground floor slab completed .
- ▮ 1st floor slab is completed.
- ▮ Brick work is in progress.
- ▮ 2nd floor slab is completed.
- ▮ Plaster work is in progress.
- ▮ Roof slab is completed.
- ▮ POP work is in progress.
- ▮ Aluminium work is in progress.
- ▮ Fire work is in progress.
- ▮ Waterproofing work is in progress.
- ▮ Electrical work is in progress.
- ▮ Plumbing work is in progress.
- ▮ Flooring work is in progress.
- ▮ Internal paint work is in progress.
- ▮ External paint work is in progress.

ROAD

- ▮ Flooring work of road is completed at cl-3&4 ,cl-17&19, cl-15&33, cl-20&21, 22&23,31&32,29&30.
- ▮ Landscape work is completed.
- ▮ Road Flooring work is in progress in front of club.