

JADE GROVE-I

1. **Status and construction of building with photograph-** mentioning blocks, each floor starting from floor-1 and construction status.

- **Piling work** :100% work complete
- **Sub Structure** :100% work complete
- **Super Structure** :
 - 1st floor RCC work-100% complete
 - 2nd floor RCC work-75% completed, balance 25% in progress
 - 3rd floor slab RCC work-50% completed, balance 50% in progress
 - 4th floor slab RCC work-Column reinforcement work in progress.

2. **Construction status of internal infrastructure-photograph with description (e.g. STP, UGR)**

- **UGR & STP: RCC deck slab casting-100% completed.**

3. **Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)**

- **Lift well, Staircase-Ground floor to 2nd floor RCC work 100% completed,3rd floor RCC work in progress**
- **Fire refuge- Yet to start**