

### 1. Status and construction of each building with photograph (as on date 31-12-2025)

- **Piling Work:** 100% Completed.
- **Substructure Work:** 100% Completed
- **Superstructure Work:**
  - Upto 5<sup>th</sup> floor slab: RCC work 100% Completed.
  - 6<sup>th</sup> Floor Slab: RCC work in progress.
- **Block Work:**
  - Ground to 1<sup>st</sup> floor: Work in Progress.
- **Inside Plastering:**
  - Ground to 1<sup>st</sup> floor: Work in Progress.
- **MEP works:**
  - Fire Protection 1st fix Work in progress at Upper Ground Floor level.

### 2. Construction status of internal infrastructure-photograph with description (e.g. STP, UGR):

- **STP:** RCC Structural work 100% Completed. Equipment Room & Tank's internal waterproofing work is in progress.
- **UGR:** RCC Structural work 100% Completed. Pump Room Waterproofing done. Tank's internal waterproofing work is in progress.
- **External Drainage Work:** 20 % of external drainage work completed in East and South side of the building.

### 3. Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)

- **Lift wall & Stair Case:**
  - RCC Structural work 100% Completed upto 5th floor slab level.
- **Fire Refuge Platform:**
  - RCC Structural work Completed at 5th floor slab level. Finishing work yet to be started.