

### Status of Internal Infrastructure

<b>Construction Status of Internal Infrastructure</b>	
RCC	
Brick Work	Completed.
Internal plaster	Completed.
Putty	All Completed
Plumbing	All completed including Above roof.
Electrical	Wiring completed 60 nos flats & switch board fixing 50 flats completed,
MS railing & Pargola	All balcony, ac leadge and pargola completed.
Acid wash-grouting and cp fittings complete	53 flats complete, 07 flats wip
Tiles & Granite	Completed A,B,C,D,E,F type flat upto 11th floor. Both side Lift Facia, 1st
External Plaster	All Completed including Above roof.
Windows and doors	Completed upto 11th floor. GF WIP
AC installation	Low side work completed 1st to 11 th floor. High wall work WIP.

### Status of Common Area

<b>Construction Status of Common area</b>		Construction Status
RCC	All completed.	
RCC above roof	All Completed	
Brick Work	All completed.	
Plumbing Work	Common area plumbing work complete & roof ring line work completed.	
Plaster	GF to roof, Above roof all plaster completed. All side elevation external wall plaster completed.	
Electrical work	Lift facia and ground floor light fixing completed, Others area completed	
Putty and paint	04 nos stair case and 02 nos lift lobby, gym room, community hall putty and paint completed, GF & boundary	
Tiles	1st to 11th floor completed, roof and ground floor completed.	
Railing	Stair railing fixing completed	
Marble Work	All marble work completed.	
Granite Work	All granite work completed	
Door & window	All door & windows completed except 1E & 10C.	
AC Installation	Community hall and gym ac installation completed, indoor game room ac installation wip	
Amenities	Community hall, Tv lounge area interior work complete. Only Indoor games WIP	
Swimming pool	Total completed.	
Gym room	Electrical work completed, colour, flooring complete, mirror fixing completed, light fixing completed.	
External Paint	External paint cc External paint 95% completed.	
MS pergola & cabana	First floor and rc First floor, roof cabana & pergola and main gate completed, Ground floor pergola wip.	
Besment	Besment waterproofing, flooring, plaster completed & Fire work completed and Paint also completed.	
Waterproofing	Roof 80% compl UGR tank, 04 nos over head tank water, roof waterproofing completed.	
CESC connection status	Feeder piller installation completed and cable laying wip	
Fire work	Fire work completed besment & first floor , stair case, besmet area completed, pump room area work started.	
Rainwater harvesting tank	Structural work complete. only filter area gravel filling incomplete	

Description	Construction Status
Paver block fixing	70% completed. At Paver block fixing completed
Granite Work	Granite work wip. Completed.
Boundary wall	North, east and west All side boundary wall completed.
Open spaces around block	Drive way casting & paver block completed, ground floor planter brick work and soil filling & plantation