

Construction Status of Common area	Construction Status
RCC	All completed.
RCC above roof	All Completed
Brick Work	All completed.
Plumbing Work	All completed.
Plaster	All completed.
Electrical work	Lift facia and grc All completed.
Putty and paint	All completed.
Tiles	All completed.
Railing	Stair railing fixing completed
Marble Work	All marbel work completed.
Granite Work	All granite work completed
Door & window	All door & windows completed except 1E & 10C.
AC Installation	Commounity hall and gym ac installation completed, indoor game room ac
Amenities	Commounity hall, Tv lounge area interior work complete. Only Indoor game
Swimming pool	Total completed.
Gym room	Electrical work completed, colour, flooring complete, mirror fixing complete
External Paint	External paint co Externall paint 95% completed.
MS pergola & cabana	First floor and ro First floor, roof cabana & pergola and main gate complete
Besment	Besment waterproofing, flooring, plaster completed & Fire work completed
Waterproofing	Roof 80% compl; UGR tank, 04 nos over head tank water, roof waterproffing
CESC connection status	Feeder piller inst Feeder piller installation completed.
Fire work	Fire work comple All completed with fire pump installation. And some fire pi
Rainwater harvesting tank	Structural work c Complete, only filter area gravel filling incomplete
Description	Construction Status
Paver block fixing	70% completed. A Paver block fixing completed
Granite Work	Granite work wip. Completed.
Boundary wall	North, east and w All side boundary wall completed.
Open spaces around block	Drive way casting & paver block completed, ground floor planter brick