

THE KOLKATA MUNICIPAL CORPORATION WATER SUPPLY DEPARTMENT

SAVE WATER SAVE LIFE

SANCTION ORDER

SAVE WATER SAVE LIFE

(Sanction/Permission for private water supply connection/or

Other works under provisions of sections

i) 258 read with sec. 558

ii) 254 read with sec. 260

iii) 235,236,239 read with sec. 260 of CMC Act, 1980)

2021120411 Building Case No .:

2022120066

Date: 21/03/2022 Date: 28/04/2022

Building Plan Sanction No .:

Borough No.: 12

Ward No.: 109

Assessee No.:

311090860098

Premises No. & Street Name:

2966

NAYABAD

Owner Name:SRI SUKUMAR GHOSH,

Name of KMC Licensed Plumber:

SRI SAJAL ROY

Address of Plumber: d-22/8, RABINDRAPALLY BLOCK 'D' .. 700086

Purpose: CONSTRUCTION

Budget Code	Description	Amount
4231/211	Deposit money for water connection - 4231/211	0
4231/212	Road opening fees - 4231/212	356
4231/231	Extra road restoration - 4231/231	10666
4210/221	Annual fees for domestic purpose water supply - 4210/221	. 0
4210/262	Sale of water for non domestic purpose (ICI) - 4210/262	0
4210/299	Miscellaneous - 4210/299	325
4231/211	Fees for water connection - 4231/211	10000

Total Amount: 21347

Receipt No.: E/07/2022/658

Date: 26/04/2022

Mode of Payment: Online Details of Water Fittings:

Stop Cock Size: 20

Service Pipe Size: 20

Water Tap Size: 12.70MD Ferrule Size:

Road Opening Date:

From 25.05.2022 to 26.05.2022

Note:
1) The above demand amount excludes physical execution of the work through KMC licensed plumber involving material, manpower & tools & plant cost.

2) Owners of the premises shall have to maintain all water fittings to prevent stagnation due to leakage & drain off water once a week from underground & overhead reservoirs and covered properly with well fitted lids for safeguard against contamination and mosquito breeding. Non-compliance may lead to cut off water connection u/s 275(b) of CMC Act, 1980 and will be treated as offence u/s 496 of the CMC Act. Ball cock is to be installed at underground reservoir to save water. It is also encouraged to install automatic pump tripping arrangement to avoid overflow from overhead reservoir.

and document, it does not require actual signature ** ** As this is a computation

Assistant Engineer Executive Engineer (W.S)