

SAVE WATER SAVE LIFE

SAVE WATER SAVE LIFE



THE KOLKATA MUNICIPAL CORPORATION

Water Supply Department

SANCTION ORDER

(Sanction/Permission for private water supply connection/or

Other works under provisions of sections

i) 258 read with sec. 558

ii) 254 read with sec. 260

iii) 235,236,239 read with sec. 260 of CMC Act, 1980)

Plan Case No.:2024100062 Submission Date:29/05/2024 Print Date:03/12/2024
 Sanction No.:2024100196 Sanction Date:03/12/2024
 Borough No.:10 Ward No.:094
 Assessee No.:210940600273 Owner Name:SMT. RAMALA BANERJEE, SRI SAMIT KUMAR BANERJEE,
 Premises No.:15A Street Name:JUBILEE PARK
 Name of KMC Licensed Plumber:SRI GOUTAM NATH
 Address of Plumber:BABURAM GHOSH RD. CAL-40. 700040
 Purpose:CONSTRUCTION Nature of Connection:NEW

Budget Code	Description	Amount
4210/221	Annual fees for domestic purpose water supply - 4210/221	0
4210/262	Sale of water for non domestic purpose (ICI) - 4210/262	0
4231/212	Road opening fees - 4231/212	356
4231/231	Extra road restoration - 4231/231	21252
4210/299	Miscellaneous - 4210/299	374
4231/211	Fees for water connection - 4231/211	20000
4231/211	Deposit money for water connection - 4231/211	0

Total Amount: 41982 Receipt No.: E/07/2024/5000 Date: 02/12/2024

Mode of Payment: Online

Details of Water Fittings: Road Opening Date: From..... To.....

Stop Cock Size:25	Service Pipe Size:25	Water Tap Size:15	Ferrule Size(mm):20
-------------------	----------------------	-------------------	---------------------

Note:

- 1) The above demand amount excludes physical execution of the work through KMC licensed plumber involving material, manpower and tools and plant cost.
- 2) Owners of the premises shall have to maintain all water fittings to prevent stagnation due to leakage and drain off water once a week from underground and overhead reservoirs and covered properly with well fitted lids for safeguard against contamination and mosquito breeding. Non-compliance may lead to cut off water connection u/s 275(b) of CMC Act, 1980 and will be treated as offence u/s 496 of the CMC Act. Ball cock is to be installed at underground reservoir to save water. It is also encouraged to install automatic pump tripping arrangement to avoid overflow from overhead reservoir.

** As this is a computer generated document, it does not require actual signature **

Assistant Engineer(W.S)

Executive Engineer(W.S)