

19/11/2022

KOLKATA MUNICIPAL CORPORATION

WATER SUPPLY DEPARTMENT

SAVE WATER SAVE LIFE

SANCTION ORDER

SAVE WATER SAVE LIFE

(Sanction/Permission for private water supply connection/or Other works under provisions of sections

i) 258 read with sec. 558

ii) 254 read with sec. 260

iii) 235,236,239 read with sec. 260 of CMC Act,

Building Case No.: 2022100015 Date: 09/04/2022

Building Plan Sanction No .:

Date: 16/08/2022

2022100102

Assessee No.:

210960701914

Borough No.: 10

Ward No.: 096 177/5/1 RAIPUR ROAD

Premises No. & Street Name:

Owner Name:SMT SAMARPITA NANDI, SMT SIMA B

Name of KMC Licensed Plumber:

SRI SUJOY DAS

Address of Plumber: 111, BISHALAKSHMI TOLA ROAD 700060

Purpose: CONSTRUCTION

NEW

Budget Code	Description	Amount
42::0/221	Annual fees for domestic purpose water supply - 42	10/221 0
4210/262	Sale of water for non domestic purpose (ICI) - 421	0/262
4231/212	Road opening fees - 4231/212	356
4231/231	Extra road restoration - 4231/231	, 4479
42:10/299	Miscellaneous - 4210/299	374
4231/211	Fees for water connection - 4231/211	20000
4231/211	Deposit money for water connection - 4231/211	0

Total Amount: 25209

Receipt No.: E/07/2022/2876

Date: 11/08/2022

Mode of Payment: Online

Details of Water Fittings:

Stop Cock Size: 25

Service Pipe Size: 25,15

Water Tap Size: 15

Ferrule Size:

Roa Dening Date:

From

22/11/2012

to

1) Ine above demand amount excludes physical execution of the work through KMC licensed plumber involving material, manpower & tools & plant post.

2) Owners of the premises shall have to maintain all water fittings to prevent stagnation due to leakage & drain off water once a week from underground & overhead reservoirs and covered property with well fitted lids for safeguard against contamination and mosquito breeding. Non-compliance/may lead to cut off water connection u/s 275(b) of CMC Act, 1980 and will be treated as offence u/s 496 of the CMC Act. Ball cock is to be installed at underground reservoir to save water. It is also encouraged to install automatic pump tripping arrangement to avoid overflow from overhead reservoir.

please orrange far bunching

S. Sarken

ين المالة 15 this is a computer generated document, it does not require actual

BE CC,

Assistant Engineer (W.S)

Mngineer (W.S)

Executive Engineer Wax Supply (South) Kolkay Municipal Corporation