

SURANJAN DUTTA

B.E.(Civil) MIE,CE
CHARTARD ENGINEER, REGD. NO. M0353
KMC E.S.E. CLASS-I NO.220
50A, SANTOSHPUR EAST ROAD,
KOLKATA - 700 075.
Ph. No. 2416 6480

TO

20X, K.P. ROY LANE, DHAKURIA, KOLKATA - 700031

Subject: Certificate of Percentage of Completion of Construction Work of **ASHRAY** [RERA Registration no **WBRERA/NPR-002861**] situated Premises No 20X, K.P. Roy Lane, P.S. Garfa Kolkata-700031, under Word No -92

STRUCTURAL ENGINEER CERTIFICATE

SL NO.	DESCRIPTION	DETAILS
1.	BUILDING /WING NUMBER (to to be prepared separately for each Building /Wing of the Project)	1
2.	Excavation* (Percentage of work done)	100 % Completed
3.	Plinth (Percentage of work done)*	100 % Completed
4.	Number of Basement(s) and Plinth*	NA
5.	Podiums Percentage of work done*	NA
6.	Number of Podiums	NA
7.	Stilt Floor Percentage of work done*	NA
8.	Slabs of Super Structure Percentage of work done*	100 % Completed
9.	Number of slabs of super structure	4 Nos
10.	Intimal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises Percentage of work done*	70 %
11.	Sanitary Fittings within the Flat/Premises Percentage of work done*	0 %
12.	Electrical Fittings within the Flat/Premises Percentage of work done*	0 %
13.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks Percentage of work done*	60 %

SURANJAN DUTTA

B.E.(Civil) MIE,CE
 CHARTARD ENGINEER, REGD. NO. M0353
 KMC E.S.E. CLASS-1 NO.220
 50A, SANTOSHPUR EAST ROAD,
 KOLKATA - 700 075.
 Ph. No. 2416 6480

14.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing Percentage of work done*	70 %
15.	Installation of lifts, water pumps and Equipment as per CFO NOC. Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ. NOC. Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate Percentage of work done*	0 %
16.	Architect Certificate regarding progress of work.	0 %

COMMON AREAS AND FACILITIES, AMENITIES DETAILS

SL NO.	DESCRIPTION	DETAILS
1.	Internal Roads & Footpaths Percentage of work done*	NA
2.	Water Supply Percentage of work done*	0 %
3.	Sewerage (chamber lines. Septic Tank. STP) Percentage of work done*	80 %
4.	Storm Water Drains Percentage of work done*	NA
5.	Landscaping & Tree Planting Percentage of work done*	NA
6.	Street Lighting Percentage of work done*	NA
7.	Community Buildings Percentage of work done*	NA
8.	Treatment and disposal of sewage and sullage water Percentage of work done*	NA
9.	Solid Waste management & Disposal Percentage of work done*	NA
10	Water conservation, Rain water harvesting Percentage of work done*	NA

SURANJAN DUTTA

B.E.(Civil) MIE,CE
CHARTARD ENGINEER, REGD. NO. M0353
KMC E.S.E. CLASS-1 NO.220
50A, SANTOSHPUR EAST ROAD,
KOLKATA - 700 075.
Ph. No. 2416 6480

11.	Energy management Percentage of work done*	NA
12.	Fire protection and fire safety requirements Percentage of work done*	NA
13.	Electrical meter room, sub-station, receiving station Percentage of work done*	NA

Yours Faithfully


Suranjan Dutta
B.E. CIVIL, MIE,CE,
KMC, E.S.E. Class-1/220
50A, East Road, Santoshpur
Kolkata-75

Signature & Name
IN BLOCK LETTERS of E.S.E.