SAMBIT CHATTERJEE

ARCHITECT

Address: 87, R.K Street, Uttarpara, Hooghly, PIN 712258.

(M) 8910182428.

SUB: Architect Certificate till 30.06.2024 for a G+3 Storied residential Building Namely M.Q RESIDENCY situated at Mouza - KAIKHALI, JL No. 05, R.S. No. 150, R.S./L.R. Dag No. 357, L.R. Khatian No. 2202, 2203, 2204, Ward No. 06, P.S- Airport, Under Bidhannagar Municipal Corporation.

WBRERA No. WBRERA/P/NOR/2023/000717

	ARCHITECT CERTIFICA	DETAILS	
SLNO.	DESCRIPTION	1	
• 4 10	BUILDING / WING NUMBER		
	(to be Prepared separately for each Building /		
	Wing of the Project)	100%	
	Excavation* (Percentage of work done)		
	Dasements) and	Basement – Not Applicable	
•	(Percentage of work done)	Plinth – 100 %	
ŀ.	Number of Basement(s) and Plinth*	Basement – 0	
	Trained as a second sec	Plinth – 1	
	Podiums Percentage of work done*	Not Applicable	
		Not Applicable	
	Number of Podiums*	100%	
	Stilt Floor	10070	
	Percentage of work done*	75 %	
	Slabs of Super Structure Percentage of	73 70	
	work done*		
	Number of Slabs of Super Structure	4 Nos.	
	Internal walls, Internal Plaster, Floorings	60 %	
0.	within Flats/Premises, Doors and Windows		
	to each of the Flat/Premises		
	to each of the Flav Fernises		
	Percentage of work done* Sanitary Fittings within the Flat/Premises	30 %	
	Percentage of work done*		
	Percentage of work done	30%	
2.	Electrical Fittings within the Flat/Premises		
	Percentage of work done*	75 %	
3.	Staircases, Lifts Wells and Lobbies at	73 70	
	each Floor level connecting Staircases		
1	and Lifts, Over head and Underground		
	Water Tanks Percentage of work done*		
1	The external plumbing and external plaster,	0 %	
14.	elevation, completion of terraces with water		
	proofing of the Building/Wing		
	Percentage of work done*		
	Percentage of work done*		

SAMBIT CHATTERJEE

Address: 87, R.K Street, Uttarpara, Hooghly, PIN 712258.

(M) 8910182428.

		==============
15.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be Required to Obtain Occupation / Completion Certificate Percentage of work done* Architect Certificate regarding progress	
1	Of work.	

COMMONAREASANDFACILITIES, AMENITIESDETAILS **DETAILS** DESCRIPTION SLNO. Internal Roads & Footh paths Percentage NA 1. of work done* Water Supply Percentage of work 90% 2. done Sewerage (chamber, lines, Septic Tank ,0% 3. STP) Percentage of work done* Storm Water Drains Percentage of work NA 4. done* Landscaping & Tree Planting Percentage of NA 5. work done* Street Lighting Percentage of work done* NA 6. Community Buildings Percentage of work NA Treatment and disposal of sewage and 8. sullage water Percentage of work done* Solid Waste management & Disposal 0% 9. Percentage of work done* Water conservation, Rain water harvesting 10. Percentage of work done* Energy management Percentage of work NA 11. Fire protection and fire safety requirements NA 12. Percentage of work done* sub-station, 25% Electrical room, meter 13. receiving station Percentage of work done*

Page 2 of 2

SAMBIT CHATTERJEE REGISTERED ARCHITECT CA/2003/32116