LALTU DEY

Consulting Engineer

TO WHOM IT MAY CONCERN

LBS CERTIFICATE

SL NO.	DESCRIPTION	DETAILS
1	BUILDING /WING NUMBER (to to be	
	prepared separately for each Building	ONE
	/Wing of the Project)	
2.	Excavation*	
	(Percentage of work done)	100%
3.	Basement(s) and Plinth	
	(Percentage of work done)*	100%
4.	Number of Basement(s) and Plinth*	ONE
5.	Podiums	
	Percentage of work done*	NA
5.	Number of Podiums*	NA
7. 8.	Stilt Floor	
	Percentage of work done*	0 %
	Slabs of Super Structure	0.07
	Percentage of work done*	0 %
Ω	Number of Slabs of Super Structure	FIVE
9. 10.	Internal walls, Internal Plaster, Floorings within Flats/	FIVE
10.	Premises, Doors and Windows to each of the Flat/ Premises	0 %
	Percentage of work done*	0 70
11.	Sanitary Fittings within the Flat/Premises	0.07
	Percentage of work done*	0 %
12.	Electrical Fittings within the Flat/Premises	0.07
	Percentage of work done*	0 %
13.	Staircases, Lifts Wells and Lobbies at each Floor level	100/
	connecting Staircases and Lifts, Overhead and	10%
	Underground Water Tanks	
	Percentage of work done*	- Participant
14.	The external plumbing and external plaster, elevation,	0.07
	completion of terraces with waterproofing of the Building/	0 %
	Wing Percentage of work done*	
15.	Installation of lifts, water pumps, Fire Fighting Fittings and	0.0/
	Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to	0 %
	conditions of environment/ CRZ NOC, Finishing to	
	entrance lobby/s, plinth protection, paving of areas	
	appurtenant to Building/Wing, Compound Wall and all	
	other requirements as may be required to Obtain	
	Occupation/Completion Certificate Percentage of work	
	done*	
16.	LBS Certificate regarding progress of work.	ATTACHED
10.	bbb certificate regarding progress of work.	MIMORED

LALTU DEY

Consulting Engineer

COMMON AREAS AND FACILITIES, AMENITIES DETAILS

SL NO.	DESCRIPTION	DETAILS
1.	Internal Roads & Foothpaths	
	Percentage of work done*	0 %
2.	Water Supply	
	Percentage of work done*	0 %
3.	Sewerage (chamber, lines, Septic Tank,	
	STP) Percentage of work done*	75%
4.	Storm Water Drains	TITLE AND AND THE TOTAL AND
	Percentage of work done*	0 %
5.	Landscaping & Tree Planting	
	Percentage of work done*	0 %
6.	Street Lighting	
	Percentage of work done*	0 %
7.	Community Buildings	
	Percentage of work done*	NA
8.	Treatment and disposal of sewage and sullage water	The state of the s
	Percentage of work done*	0 %
9.	Solid Waste management & Disposal	*//
	Percentage of work done*	0 %
10.	Water conservation, Rain water harvesting	
	Percentage of work done*	0 %
11.	Energy management	
	Percentage of work done*	0 %
12.	Fire protection and fire safety requirements	
	Percentage of work done*	0 %
13.	Electrical meter room, sub-station, receiving station	
	Percentage of work done*	0 %

Thanking you,

Yours Faithfully,

Laltu Dey,

B.E. (Civil), M.I.E, Chartered Engineer (India)

DMC Licence No. - DMC/BPD/144

B.E. (CIVIL), M.I.E.
Chartered Engineer (India)
Licence No.-DMC/BPD/144
Durgapur Municipal Corporation