LALTU DEY

Consulting Engineer

TO WHOM IT MAY CONCERN

LBS CERTIFICATE

SL NO.	DESCRIPTION	DETAILS
1	BUILDING /WING NUMBER (to to be prepared separately for each Building /Wing of the Project)	ONE
2.	Excavation* (Percentage of work done)	100%
3.	Basement(s) and Plinth (Percentage of work done)*	100%
4.	Number of Basement(s) and Plinth*	ONE
5.	Podiums Percentage of work done*	NA
6. 7.	Number of Podiums*	NA
7.	Stilt Floor Percentage of work done*	50 %
8.	Slabs of Super Structure Percentage of work done*	0 %
9.	Number of Slabs of Super Structure	FIVE
10.	Internal walls, Internal Plaster, Floorings within Flats/ Premises, Doors and Windows to each of the Flat/ Premises Percentage of work done*	0 %
11.	Sanitary Fittings within the Flat/Premises Percentage of work done*	0 %
12.	Electrical Fittings within the Flat/Premises Percentage of work done*	10 %
13.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks Percentage of work done*	20%
14.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing Percentage of work done*	0 %
15.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/ CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation/Completion Certificate Percentage of work done*	0 %
	I DC Contiguets regarding progress of week	

16. LBS Certificate regarding progress of work. **ATTACHED**

39, Ground Floor, East Avenue, Bengal Ambuja, DGP-16

MOBILE-9434232377, 8637586033, Email Id: laltude 2004 @ gmail to Durgapur Municipal Corporation

LALTU DEY

Consulting Engineer

COMMON AREAS AND FACILITIES, AMENITIES DETAILS

SL NO.	DESCRIPTION	DETAILS
1.	Internal Roads & Foothpaths	
	Percentage of work done*	0 %
2.	Water Supply	
	Percentage of work done*	0 %
3.	Sewerage (chamber, lines, Septic Tank,	34-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
	STP) Percentage of work done*	85%
4.	Storm Water Drains	
	Percentage of work done*	0 %
5.	Landscaping & Tree Planting	
20.0	Percentage of work done*	0 %
6.	Street Lighting	
	Percentage of work done*	0 %
7.	Community Buildings	
	Percentage of work done*	NA .
8.	Treatment and disposal of sewage and sullage water	
	Percentage of work done*	0 %
9.	Solid Waste management & Disposal	
	Percentage of work done*	0 %
10.	Water conservation, Rain water harvesting	
	Percentage of work done*	0 %
11.	Energy management	
	Percentage of work done*	0 %
12.	Fire protection and fire safety requirements	
	Percentage of work done*	0 %
13.	Electrical meter room, sub-station, receiving station	× = .
	Percentage of work done*	0 %

Thanking you,

Yours Faithfully,

B.E. (CIVIL), M.I.E.
Chartered Engineer (India)
Licence No.-DMC/BPD/144
Durgapur Municipal Corporation

Laltu Dey,

B.E. (Civil), M.I.E, Chartered Engineer (India)

DMC Licence No. - DMC/BPD/144