ARCHITECT CERTIFICATE

SLNO.	DESCRIPTION	DETAILS
1.	BUILDING/WINGNUMBER(to be Prepared separately for each Building /Wing of the Project)	No of Building : One
2.	Excavation* (Percentage of work done)	100% Completed
3.	Basement(s) and Plinth	Plinth work 100% Completed
	(Percentage of work done)*	
4.	Number of Basement(s) and Plinth*	NA
5.	Podiums Percentage of work done*	NA .
6.	Number of Podiums*	NA
7.	Stilt Floor Percentage of work done*	NA
8.	Slabs of Super Structure Percentage of work done*	Work in Progress
9.	Number of Slabs of Super Structure	6 Nos
10.	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises Percentage of work done*	0%
11.	Sanitary Fittings within the	0%
	Flat/Premises Percentage of work done*	Andry
12.	Electrical Fittings within the Flat/Premises Percentage of work done*	0%
13.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks Percentage of work done*	0%
14.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing Percentage of work done*	0%
15.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas,	0%
	electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of	

KAUSHIK ABHILASH DASGUPTA B.ARCH

REG. NO. CA/2003/30828 COUNCIL OF ARCHITECTURE ARCH/HIDCO/09/00038

	Are as appurtenant to Building/Wing,	
	Compound Wall and all other	
	requirements as may be	
	Required to Obtain Occupation	
	/Completion Certificate	
	Percentage of work done*	
16	Architect Certificate regarding progress	
16.	Of work.	
	THE PARTY OF THE P	TIES DETAILS

COMMON AREAS AND FACILITIES, AMENITIES DETAILS

	DESCRIPTION	DETAILS
SLNO.	DESCRIPTION	0%
1.	Internal Roads & Footh paths	
	Percentage of work done*	0%
2.	Water Supply	
	Percentage of work done*	0%
3.	Sowerage (chamber, lines, Septic Tank,	070
3.	STP) Percentage of work done*	
	Sirjiereems	
	Storm Water Drains	0%
4.	Percentage of work done*	
	Percentage of Work density	0%
5.	Landscaping & Tree Planting	
	Percentage of work done*	0%
6.	Street Lighting	
	Percentage of work done*	0%
7.	Community Buildings	070
/.	Percentage of work done*	0%
8.	Treatment and disposal of sewage and	070
8.	sullage water	
	Percentage of work done*	
	reicentage of worst	
	Solid Waste management & Disposal	0%
9.	Percentage of work done*	
	Percentage of work done	0%
10.	Water conservation, Rain water	
	harvesting	
	Percentage of work done*	0%
11.	Energy management	
11.	Percentage of work done*	0%
12.	Fire protection and fire safety	070
12.	requirements	
	Percentage of work done*	
	Electrical meter room, sub-station,	0%
13.	receiving station	
	Percentage of work done*	
	Percentage of work done	

KAUSHIK ABHILASH DASGUPTA B.ARCH

REG. NO. CA/2003/30828 COUNCIL OF ARCHITECTURE ARCH/HIDCO/09/00038