


A photograph of a long, narrow hallway on the ground floor of Block 3. The floor is covered in square tiles with a repeating geometric pattern of interlocking squares and stars. The walls are white but show significant signs of wear and damage, particularly on the right side where the plaster is peeling and the underlying brickwork is exposed. A single window is visible at the far end of the hallway, letting in natural light. Some debris, including a yellow bag and some papers, is scattered on the floor further down the hallway. A small, rectangular object, possibly a brick or a piece of wood, lies on the floor in the foreground on the right side.

Block - 3 Ground floor