

Work Status :-

Block D & E :

2nd Floor, 3rd Floor & 4th Floor roof casting completed for Block D & E.

Lift room, mummy room & Overhead Tank casting completed for Block D & E.

1st, 2nd & 3rd floor Brick work in progress of Block D & E.

Block C :

Plinth work in progress of Block C.

Block A & B :

Construction not yet started.