



*Block-3
Floor-15
Flat-H*

Block-3
Floor-15
Flat-G





*Block-3
Floor-3
Flat-G*



*Block-3
Floor-14
Flat-H*

A photograph of a construction site interior. The space is filled with wooden formwork and metal beams. In the foreground, there are several long, perforated metal beams stacked on the floor. The walls and ceiling are made of wooden panels, some of which are labeled with handwritten text like 'CL-17' and 'CL-18'. A bright light source is visible in the background, creating a strong contrast. The overall scene depicts a busy construction environment.

Block-3
Floor-15

Flat-1



*Block-3
Floor -13
Flat-G*



*Block-3
Floor -14
Flat-1*



*Block-3
Floor-13
Flat-1*



*Block-3
Floor -13
Flat-H*



Block-3
Floor -12
Flat -G

Block-3
Floor -12
Flat -I





Block-3
Floor -11
Flat-H



Block-3
Floor -12
Flat -H



Block-3
Floor -11
Flat-G

Block-3
Floor -10
Flat -G





Block-3
Floor -11
Flat -I



Block-3
Floor -10
Flat -I



Block-3
Floor -10
Flat -H

The image shows the interior of a flat under construction. The walls are white and appear to be freshly plastered. The floor is a rough, grey concrete surface. In the foreground, there are several long, black, flexible pipes or conduits lying on the floor. A doorway in the background leads to another room. The ceiling has some small, dark spots, possibly from construction or lighting fixtures. The overall lighting is somewhat dim, typical of an interior space under construction.

Block-3
Floor -9
Flat -H



Block-3
Floor -9
Flat -I



The image shows the interior of a flat under construction. The walls are white and appear to be in the final stages of finishing. The floor is a light-colored, possibly concrete or plaster, and is covered with some debris and dust. A large window at the far end of the room provides natural light. In the foreground, a large number of black pipes are stacked on the floor, along with some cardboard boxes and other construction materials. The overall atmosphere is one of a work-in-progress space.

Block-3
Floor-9
Flat -G



Block-3
Floor -8
Flat -H

The image shows the interior of a building under construction. The walls are white and the floor is a mix of concrete and dirt. There are some pipes and construction materials visible. A large white box with black text is overlaid in the center. The text reads:

Block-3
Floor -8
Flat -1



Block-3
Floor -8
Flat -G

The image shows the interior of a flat during renovation. The walls are white but show signs of wear and peeling paint at the base. The floor is made of large, light-colored tiles with a grid pattern. In the background, there is an open doorway leading to another room. On the floor near the doorway, there is a cardboard box, some pipes, and other construction debris. A black cable runs across the floor in the foreground.

Block-3
Floor-7
Flat -H

A photograph of an interior construction site. In the foreground, a man in a pink shirt is crouching on the floor, which is covered with large wooden panels and some debris. In the background, three other men are standing near a doorway. One man is wearing a yellow shirt, another a grey shirt, and a third a blue shirt with a red headscarf. The walls are white and have some small, dark rectangular openings. The ceiling is also white. The overall scene suggests a renovation or construction project in progress.

Block-3
Floor -7
Flat -I

The image shows the interior of a flat under construction. The walls are white and appear to be in the final stages of plastering. The floor is a rough, grey concrete. A large window at the far end of the room is covered with a metal frame and scaffolding, suggesting it might be a balcony or a large window. To the left, there is a doorway leading to another room. On the right side, several large, rectangular tiles or panels are leaning against the wall. The overall atmosphere is one of a raw, unfinished space.

Block-3
Floor -7
Flat -G

The image shows a room with white walls and a concrete floor. There are some dark spots and stains on the wall and floor. A doorway is visible on the right side, leading to another room. In the background, there are some wooden boards and pipes. A white text box is overlaid in the center of the image.

Block-3
Floor -6
Flat-H

The image shows the interior of a flat during renovation. The floor is covered with blue protective sheets, some of which are secured with brown straps. A doorway on the left leads to a darker area. In the background, another room is visible through an opening. A red pipe runs along the ceiling. A white text box is centered in the image.

Block-3
Floor -6
Flat -I



Block-3
Floor -6
Flat- G

Block-3
Floor-5



Block-3
Flat -G side
Floor -5





Block-3
Floor-3

A photograph of a dark, narrow corridor or tunnel. The walls are made of concrete blocks, and the floor is also concrete. A bright light source is visible at the end of the corridor, creating a strong glare. The text "Block-3" and "Floor -4" is overlaid on the image in a white box.

Block-3
Floor -4



Block-3
Floor -2









Block-3

MKG



Block-3
Floor-1