

Block 19

Status of Construction

Piling Complete, Foundation Complete, Ground Floor Complete, 1st Floor To Roof Rcc Completed And Above Roof Rcc Completed. Brick Work 1st To 12th Floor Complete, Above Roof Brick Work Completed. Outside Plaster Complete. Waterproofing Complete.

Construction Status of Internal Infrastructure

Inside Plaster 1st To 12th Floor Complete. Inside Plumbing 1st To 12th Floor Complete. Inside Electrical 1st To 12th Floor Complete. Inside Putty Work 1st To 12 Floor Ongoing. Flooring Work 1st To 12th Floor Complete. Aluminium Window 1st To 12 Floor Ongoing. Toilet False Ceiling 1st To 12th Floor Complete. Stair And Balcony Railing 1st To 12th Floor Complete. Fire Riser Ms Pipe 1st To 12th Floor Complete. Lift Installation Ongoing.

Construction Status of Common area

Main Gate And Back Gate – Completed

Fire Pump - Completed For All Block