

NUMA

1. Status and construction of each building with photograph

(as on date 30-06-2026)

- **Piling Work:**
 - **Block 1** – On going. 49% completed.
 - **Block 2** – Completed.
- **Substructure Work:** Foundation Work Not Started.
- **Superstructure Work:** Not Started
- **Internal Finishing Work:** Not Started
- **MEP works:** Not Started

2. Construction status of internal infrastructure-photograph with description (e.g. STP, UGR):

- **STP:** Not Started
- **UGR:** Not Started
- **External Drainage Work:** Not Started

3. Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)

- **Lift wall & Stair Case:** Not Started
- **Fire Refuge Platform:** Not Started