

NUMA

1. Status and construction of each building with photograph

(as on date 31-03-2026)

- **Piling Work:** 44% Completed (Overall Project)
- **Substructure Work:** Not Started.
- **Superstructure Work:** Not Started.
- **Internal Finishing Work**
 - **Block Work:** Not Started.
 - **Inside Plastering:** Not Started.
 - **Flooring:** Not Started.
 - **Door Window:** Not Started.
- **MEP works:**
 - Not Started

2. Construction status of internal infrastructure-photograph with description (e.g. STP, UGR):

- **STP:** Not Started.
- **UGR:** Not Started.
- **External Drainage Work:** Not Started.

3. Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)

- **Lift wall & Stair Case:** Not Started.
- **Fire Refuge Platform:** Not Started.