

## **WORK STATUS OF NAVYOM \_ RERA (Status as on 4<sup>th</sup> November 2024)**

### **1. Substructure:**

- a. **Tower - 7:** 100% completed.
- b. **Tower - 8:** 100% completed.
- c. **Tower - 9:** 100% completed.
- d. **Tower - 10:** 100% completed.

### **2. Superstructure (Upto Roof Slab)**

- a. **Tower - 7:** 100% completed.
- b. **Tower - 8:** 100% completed.
- c. **Tower - 9:** 100% completed.
- d. **Tower - 10:** 100% completed.

### **3. Internal Walls & Internal Plaster:**

- a. **Tower - 7:** 100% completed.
- b. **Tower - 8:** 100% completed.
- c. **Tower - 9:** 100% completed.
- d. **Tower - 10:** 100% completed.

### **4. Internal Putty:**

- a. **Tower - 7:** 100% completed.
- b. **Tower - 8:** 100% completed.
- c. **Tower - 9:** 100% completed.
- d. **Tower - 10:** 100% completed.

### **5. Tiling Work (Inside Unit)**

- a. **Tower - 7:** 100% completed.
- b. **Tower - 8:** 100% completed.
- c. **Tower - 9:** 100% completed.
- d. **Tower - 10:** 100% completed.

### **6. Tiling Work (Common Lobby):**

- a. **Tower - 7:** 100% Completed.
- b. **Tower - 8:** 100% Completed.
- c. **Tower - 9:** 100% Completed.
- d. **Tower - 10:** 100% Completed.

### **7. UGR or Tank:**

- a. At Basement area of Tower - 7 to 10 rainwater harvesting tank RCC work completed.
- b. WTP, domestic, fire water tank and STP are situated in **PH-I** (within Tower 1 to 6 area basement): RCC completed and Electromechanical work in progress.

### **8. Infrastructure & landscaping work in progress**

- a. External Driveway:** RCC Work Complete, Kerb stone fixing complete. Paver block Fixing Pending.
- b. Landscaping:** Partial Plantation completed. Tile Work Completed. Others Finishing Work in progress.

#### **9. External Paints**

- a. Tower - 7:** 20% completed.
- b. Tower - 8:** 5% (Surface Preparation Started)
- c. Tower - 9:** 30% completed.
- d. Tower - 10:** 35% completed.