

WORK STATUS OF NAVYOM _ RERA (Status as on 2nd June 2025)

1. Substructure:

- a. Tower - 7:** 100% completed.
- b. Tower - 8:** 100% completed.
- c. Tower - 9:** 100% completed.
- d. Tower - 10:** 100% completed.

2. Superstructure:

- a. Tower - 7:** 100% completed.
- b. Tower - 8:** 100% completed.
- c. Tower - 9:** 100% completed.
- d. Tower - 10:** 100% completed.

3. Internal Walls & Internal Plaster:

- a. Tower - 7:** 100% completed.
- b. Tower - 8:** 100% completed.
- c. Tower - 9:** 100% completed.
- d. Tower - 10:** 100% completed.

4. Internal Putty:

- a. Tower - 7:** 100% completed.
- b. Tower - 8:** 100% completed.
- c. Tower - 9:** 100% completed.
- d. Tower - 10:** 100% completed.

5. Tiling Work (Inside Unit)

- a. Tower - 7:** 100% completed.
- b. Tower - 8:** 100% completed.
- c. Tower - 9:** 100% completed.
- d. Tower - 10:** 100% completed.

6. Tiling Work (Common Lobby):

- a. Tower - 7:** 100% Completed.
- b. Tower - 8:** 100% Completed.
- c. Tower - 9:** 100% Completed.
- d. Tower - 10:** 100% Completed.

7. UGR, OHR, STP & WTP:

- a.** At the Basement area of Tower 7 to 10, UGR & rainwater harvesting tank RCC work completed. All Tower OHR work completed.
- b.** WTP, domestic, fire water tank and STP are situated in PH-I (within Tower 1 to 6 area basement): RCC completed and Electro-mechanical work completed.

8. Infrastructure:

- a. **External Driveway:** RCC work complete, Kerb stone fixing complete. Paver block fixing work is completed.
- b. **Landscaping:** Plantation, Tiles work & Other finishing work completed.
- c. **MLCP:** MLCP installation work completed.
- d. **External Drainage:** External drainage work completed.
- e. **Boundary wall:** All Boundary wall work completed.

9. External Paints:

- a. **Tower - 7:** 100% completed.
- b. **Tower - 8:** 100% completed.
- c. **Tower - 9:** 100% completed.
- d. **Tower-10:** 100% completed.