

Cluster – 21

Unit – 153 to 157

- Completion of Brick Work – Completed
- Plastering Work - Completed
- Completion of Flooring – Work in progress.
- Putty Work – Pending

