

HARBOUR ONE

1. Status and construction of each building with photograph

(as on date 30-06-2026)

- **Piling Work:**
 - Block 1 – Completed.
 - Block 2 – Completed.
- **Substructure Work:**
 - Block 1 – Sheet Pile Completed. Foundation Work in Progress. Approx 40% work Completed.
 - Block 2 – Partially Completed. Approx 75%.
- **Superstructure Work:** Not Started.
- **Internal Finishing Work**
 - **Block Work:** Not Started.
 - **Inside Plastering:** Not Started.
 - **Flooring:** Not Started.
 - **Door Window:** Not Started.
- **MEP works:**
 - Not Started

2. Construction status of internal infrastructure-photograph with description (e.g. STP, UGR):

- **STP:** Not Started.
- **UGR:** Not Started.
- **External Drainage Work:** Not Started.

3. Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)

- **Lift wall & Stair Case:** Not Started.
- **Fire Refuge Platform:** Not Started.