

Project Status

1. Status of Construction of each Building and Floor with Photographs

- Block A - Excavation and Foundation Completed
 - One number of Basement and Plinth completed
 - Stilt Floor completed
 - 05 number of Slabs of Super Structure completed
- Block B - Excavation and Foundation Completed
 - One number of Basement and Plinth completed
 - Stilt Floor completed
 - 5 number of Slabs of Super Structure completed

2. Construction Status of Internal Infrastructure

- Block A - Internal Walls, Internal Plaster, Floorings going on
- Block B - Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises completed

3. Construction Status of Common area

- Block A - Staircase, Lifts Wells and Lobbies at each Floor Level connecting Staircases and Lifts, Overhead and Underground Water Tanks Started
- Block B – Staircase, Lifts Wells and Lobbies at each Floor Level connecting Staircases and Lifts, Overhead and Underground Water Tanks completed
- The External Plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building /Wing going on