

Construction Update of
Botanica-9th October,2025
PHASE-I

11.Cluster-29, Unit no.98 to 99

- ☐ Sub structure is completed.
- ☐ Ground floor slab is completed.
- ☐ Brick work is completed.
- ☐ 1st floor slab completed.
- ☐ Roof slab is completed.
- ☐ Internal Electrical work in completed.
- ☐ Plaster work is completed.
- ☐ Plumbing work is in completed.
- ☐ Flooring work is in completed.
- ☐ Finishing Work is in completed.
- ☐ External paint is in completed.

