

# 1. Cluster-03, Unit no.11 to15

- Civil substructure works complete.
- Ground floor slab completed.
- 1<sup>st</sup> floor slab completed.
- Roof slab completed
- Brickwork work completed
- Plastering work completed
- Internal Electrical Wiring work completed.
- Internal Plumbing work in completed.
- Water Proofing completed.
- Pop work is in completed.
- Anti termite work completed
- Flooring work is in completed.
- Finishing work is in completed.
- External paint is completed.

