

6.Cluster–19,Unitno.38to47

- Civilsub-structureworks foundation complete.
- Ground floor slab completed.
- Brickwork work is completed.
- First floor slab completed.
- Internal Electrical Wiring work in completed.
- Roof slab completed.
- Plastering work is completed.
- Internal Plumbing work in completed.
- Anti termite work completed.
- Waterproofing work is completed.
- Flooring work is in completed.
- Finishing work is on completed.
- External paint is in .

