

Cluster-23,Unit no. 87 to 92

- ☐ **Civil substructure works foundation completed.**
- ☐ **Ground floor slab completed.**
- ☐ 1st floor slab completed.
- ☐ Roof slab completed.
- ☐ **Brickwork work is completed.(87 to 92)**
- ☐ **Internal Electrical work in completed.**
- ☐ **Plumbing work is in completed.**
- ☐ **Plastering work is completed.**
- ☐ Anti termite work completed.
- ☐ Waterproofing work is completed.
- ☐ Flooring work is in completed.(87 to 92)
- ☐ Finishing work is on completed.
- ☐ External paint is in completed.

