

Ground Floor	Back filling 100% Completed Plinth Beam 100% completed Structure 100% Completed
1st Floor	Block Work 100% Completed Structure 100% Completed
2nd Floor	Block Work 90% Completed Structure 100% Completed
3rd Floor	Structure 100% Completed Finishing 80 % completed
4th Floor	Structure 100% Completed Finishing 80 % completed
5th Floor	Structure 100% Completed Finishing 80 % completed

6th Floor	Structure 100% Completed Finishing 80 % completed
7th Floor	Structure 100% Completed Finishing 80 % completed
8th Floor	Structure 100% Completed Finishing 80 % completed
9th Floor	Structure 100% Completed Finishing 80 % completed
10th Floor	Structure 100% Completed Finishing 80 % completed

11th Floor	Structure 100% Completed Finishing 80 % completed
12th Floor	Structure 100% Completed Finishing 70 % completed
13th floor	
14th floor	
15th floor	
16th floor	
17th floor	
18th floor	
19th floor	
20th floor	
21st floor	
22nd floor	
23rd floor	
24th floor	
25th floor	
26th floor	
27th floor	
28th floor	
29th floor	
30th floor	
31st floor	
32nd floor	