

1. **Status and construction of building with photograph-** mentioning blocks, each floor starting from floor-1 and construction status.

- **Piling work** :100% work complete.

- **Sub Structure** :100% work complete.

- **Super Structure** :

- 1<sup>st</sup> floor slab RCC work-100% completed.
- 2<sup>nd</sup> floor slab RCC work-100% completed.
- 3<sup>rd</sup> floor slab RCC work-100% completed.
- 4<sup>th</sup> floor slab RCC work-100% completed.
- 5<sup>th</sup> floor slab RCC work-100% completed.
- 6<sup>th</sup> floor slab RCC work-Slab RCC work in progress.

- **Block-work** :

- 2<sup>nd</sup> floor: Internal block work in progress.

2. **Construction status of internal infrastructure-photograph with description (e.g. STP, UGR)**

- UGR & STP: RCC deck slab casting-100% completed.

3. **Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)**

- Lift well, Staircase-Ground floor to 5<sup>th</sup> floor RCC work 100% completed, 6<sup>th</sup> floor RCC work in progress.
- Fire refuge- Yet to start.