

One-10 Phase- 2: Tower- 1, 2 & 10

- Sub Structure: 100% work completed.
- Super Structure: 100% work completed.
- Brickwork: 100% work completed.
- Plasterwork: 100% work completed.
- Finishes work: 100% work completed.

2. Construction status of internal infrastructure-photograph with description(e.g stp,ugr)

One-10 Phase- 1: Tower- 1, 2 & 10

- UGR & OHR: 100% work completed.
- Driveway: 100% work completed.
- External Drainage: 100% work completed.
- Boundary Wall: 100% work completed.
- MLCP: 100% work completed.

3. Construction Status of common area-photograph with description(e.g-lift well,fire refuge,stair case)

One-10 Phase- 1: Tower- 1, 2 & 10

- Brickwork: 100% work completed.
- Plasterwork: 100% work completed.
- Finishes work: 100% work completed.
- Stair area work: 100% work completed.
- Lift work: 100% work completed.

Aside also please find the Rera Quarterly update of Montage site attached.

1. Status and construction of building with photograph- mentioning blocks, each floor starting from floor-1 and construction status.

- Sub Structure: 100% work completed.
- Super Structure: 100% work completed.
- Brickwork: 100% work completed.
- Plasterwork: 100% work completed.
- Finishes work: 100% work completed.

2. Construction status of internal infrastructure-photograph with description(e.g stp,ugr)

- UGR & OHR: 100% work completed.
- Driveway: 100% work completed.
- External Drainage: 100% work completed.
- Boundary Wall: 100% work completed.
- MLCP: 100% work completed.

3. Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)

- Brickwork: 100% work completed.
- Plasterwork: 100% work completed.
- Finishes work: 100% work completed.
- Stair area work: 100% work completed.
- Lift work: 100% work completed