

1. **Status and construction of building with photograph-** mentioning blocks, each floor starting from floor-1 and construction status.

- **Piling work:** Piling work 100% completed (for Block-A & B)

- **Sub Structure:**

- Block B- Pile cap work, tie beam & column 100% completed.
- Block A- Earth cutting & pile cap work in progress

- **Super Structure :**

- Block B- 1st floor slab RCC 70% completed. Balance RCC work of 1st floor slab in progress.
- Block A -Yet to start.

2. **Construction status of internal infrastructure-photograph with description (e.g. STP, UGR)**

- **UGR & STP :** Earth cutting, pile cap & raft casting work in progress

3. **Construction Status of common area-photograph with description (e.g.-lift well, fire refuge, stair case)**

- **Block B- Lift well, Staircase-**Ground floor to 1st floor RCC work 100% completed, 1st to 2nd floor RCC work in progress