Up to date Finishing work progress as on 05/10/2025 of Block-3/ Type-N					
Items	Part-1	Part-2	Part-3		
MS Railing	Up to 10th floor	Up to 7th floor	Up to 4th floor		
Floor Tiles	Up to 9th floor	Up to 5th floor	Nil		
Kitchen Tiles	Up to 9th floor	Up to 3rd floor	Nil		
Toilet Floor Tiles	Up to 8th floor	Up to 3rd floor	Nil		
Toilet Wall Tiles	Up to 8th floor	Up to 2nd floor	Nil		
Balcony Floor Tiles	Up to 8th floor	Nil	Nil		
Kitchen Stand/Pedestal	Up to 8th floor	Up to 2nd floor	Nil		
(Blackstone)					
Kitchen Counter Top (Granite)	Up to 8th floor	Up to 2nd floor	Nil		
Toilet Waterproofing	Up to 9th floor	Up to 6th floor	2nd & 3rd floor		
Kitchen Waterproofing	Up to 9th floor	Up to 6th floor	2nd & 3rd floor		
Balcony Waterproofing	Up to 9th floor	Up to 6th floor	2nd & 3rd floor		
Putty work in Flat	Up to 9th floor	Up to 6th floor	Up to 5th floor		
Putty work in Lobby	Up to 9th floor	Up to 6th floor	Up to 5th floor		
Door Frame	Part of 10th floor	Up to 7th floor	Up to 3rd floor		
Plumbing wiring and filling	Up to 11th floor	Up to 9th floor	Up to 6th floor		
Bore packing & Line hanging	Up to 11th floor	Up to 9th floor	Up to 6th floor		
Pressure Test	Up to 11th floor	Up to 9th floor	Up to 6th floor		
Fire fighting sprinkler line	At stilt floor 70% work is completed.				
VDF Flooring	At stilt floor 30% work is completed.				

Up to date Finishing work progress as on 05/10/2025 of Block-1/ Type-C			
Items	Status		
MS Railing	Up to 2 nd floor work is in progress		
Plumbing wiring and filling	Up to 4th Floor work is in progress		
Toilet Waterproofing	Work is in progress at 1st Floor		
Balcony Waterproofing	Work is in progress at 1st Floor		
Putty work in flat	Work is in progress at 1st Floor		

Up to date External Development work progress as on 05/10/2025				
Road	5% Completed			
Cable trench	35% Completed			
Fire water line	80% Completed.			
Drainage line	35% completed.			
STP	Water proofing work 50% completed			
WTP	Water proofing work 50% completed			
Swimming Pool	Structure completed.			
Community Hall	Plastering and putty work is in progress.			

		1		
	Under Construction/Not			
Block-1/Type-C		sting completed and 7th Floor roof is in progre	255.	
Block-2/Parking Block	Groun	Ground floor roof slab 33% completed.		
	Part-1- Roof slab completed, F	-3- 8th floor		
Block-3/Type-N				
Construction Status of Internal Infrastructure				
Description		Image Serial No.		
Block-3/Type-N	Under Construction/Not Started/Completed Without CC/Completed With CC			
Balcony railing fixing	Up to 10th floor	Under Construction		
Water proofing	Up to 10th floor	Under Construction		
Door frame fixing	Up to 10th floor	Under Construction		
Plumbing	Up to 10th floor	Under Construction		
Tiles flooring	Up to 9th floor	Under Construction		
Kitchen flooring with plat form fixing	Up to 6th floor	Under Construction		
Wall tiles fixing in toilet and kitchen	Up to 6th floor	Under Construction		
Putty work	Up to 10th floor	Under Construction		
Construction Status of Internal Infrastructure			·	
Description	Construction Status		Image Serial No.	
Block-1/Type-C	Under Construction/Not Started/Completed Without CC/Completed With CC			
Balcony railing fixing	Up to 3rd floor	Under Construction		
Plumbing	Up to 4th floor	Under Construction		
Water proofing	Up to 1st floor	Under Construction		
Putty work	Up to 1st floor	Under Construction		
Construction Status of Common area				
Plumbing	Under Construction			
Fire	Under Construction			
Road	Under Construction			
Electrical	Under Construction			
Drainage	Under Construction			
Water treatment plant and UGR	Under Construction			
Sewerage Treatment plant	Under Construction			
Cable trench	Under Construction			