


2nd PROGRESS REPORT OF G+IV STOREID BUILDING



USHA JYOTI APARTMENT

AT WARD -22, CHAMPDANI MUNICIPALITY

Prepared By: Er Krishnendu (Enlisted LBS-I of
Champdani Municipality)


e-mail: krishnendusil@yahoo.co.in





Krishnendu Sil
KRISHNENDU SIL
ICI, MIE, MIGS
CHARTERED ENGINEER
ENLISTED ENGINEER
CHANDANNAGAR MUNICIPAL CORPORATION
M-1582393, IGS-4554, ICI-4934

GROUND FLOOR STATUS as on 10-4-22



Krishnendu Sil
KRISHNENDU SIL 10-4-22

ICI, MIE, MIGS
CHARTERED ENGINEER
ENLISTED ENGINEER
CHANDANNAGAR MUNICIPAL CORPORATION
M-1582393, IGS-4554, IC1-4934

1 st FLOOR STATUS as on 10-04-22




Dt 10-04-22

Krishnendu Sil
10-4-22

KRISHNENDU SIL
ICI, MIE, MICS
CHARTERED ENGINEER
ENLISTED ENGINEER
CHANDANNAGAR MUNICIPAL CORPORATION
M-1582393, IGS-4554, ICI-4934



2 nd FLOOR STATUS as on 10-04-22





2nd Floor Common passage

Krishnendu Sil
KRISHNENDU SIL 10-4-22
ICI, MIE, MIGS
CHARTERED ENGINEER
ENLISTED ENGINEER
CHANDANNAGAR MUNICIPAL CORPORATION
M-1582393, IGS-4554, ICI-4934

4 TH FLOOR STATUS AS on 10-04-22



Krishnendu Sil
KRISHNENDU SIL 10-4-22
ICI, MIE, MIGS
CHARTERED ENGINEER
ENLISTED ENGINEER
CHANDANNAGAR MUNICIPAL CORPORATION
M-1582393, IGS-4554, ICI-4934



Krishnendu Sil
KRISHNENDU SIL 10-4-22
ICI, MIE, MIGS
CHARTERED ENGINEER
ENLISTED ENGINEER
CHANDANNAGAR MUNICIPAL CORPORATION
M-1582393, IGS-4554, ICI-4934

ROOF STATUS AS on 10-04-22



THANK YOU

Krishnendu Sil
KRISHNENDU SIL 10-4-22
ICI, MIE, MIGS
CHARTERED ENGINEER
ENLISTED ENGINEER
CHANDANNAGAR MUNICIPAL CORPORATION
M-1582393, IGS-4554, ICI-4934