

1. Status and construction of each building with photograph- mentioning blocks, each floor starting from floor-1 and construction status.

Tower 1 : 9th Floor slab work completed. 10th floor slab work in progress.

Tower 2 : 6th Floor Slab work completed. 7th floor slab work in progress.

Tower 3 : 1st floor slab work completed. 2nd floor slab work in progress.

Tower 4 : 2nd floor slab completed. 3rd floor slab work in progress.

Podium : 76% Foundation work, 42% 1st Floor, 40% 2nd Floor Slab work completed.

Balance work in foundation, 1st Floor and 2nd Floor in progress.

2. Construction status of internal infrastructure-photograph with description(e.g stp, ugr)

UGR : Structural work has been completed.

STP : Secant pile work in progress.

3. Construction Status of common area-photograph with description(e.g. - lift well, fire refuge, stair case)

Lift

Tower 1 : Work up to 9th Floor Completed. 10th Floor work in progress.

Tower 2 : Work up to 6th Floor Completed. 7th Floor work in progress.

Tower 3 : Work up to 1st Floor Completed. 2nd Floor work in progress

Tower 4 : Work up to 2nd Floor Completed. 3rd Floor work in progress.

Podium : Work up to 1st and 2nd Floor Completed.

Fire Refuge

Tower 1 : 7th floor level fire refuge platform completed.

Tower 2 : Not reached in that level

Tower 3 : Not reached in that level

Tower 4 : Not reached in that level

Podium : No Scope

Staircase

Tower 1 : Work up to 9th Floor Completed. 10th Floor work in progress.

Tower 2 : Work up to 6th Floor Completed. 7th floor work in progress.

Tower 3 : Work up to 1st Floor Completed. 2nd Floor work in progress.

Tower 4 : Work up to 2nd Floor Completed. 3rd Floor work in progress.

Podium : Work up to 1st Floor Completed. 2nd Floor work in progress.