

1. Status and construction of each building with photograph-mentioning blocks, each floor starting from floor-1 and construction status.

- Tower 1: 11th Floor slab work completed. 12th floor slab work in progress.
- Tower 2: 7th Floor Slab work completed. 8th floor slab work in progress.
- Tower 3: 1st floor slab work completed. 2nd floor slab work in progress.
- Tower 4: 4th floor slab completed. 5th floor slab work in progress.
- Podium: 77% Foundation work, 60% 1st Floor, 52% 2nd Floor Slab work completed. 3rd floor level slab has been started. Balance work in foundation, 1st Floor and 2nd Floor, 3rd floor in progress.

2. Construction status of internal infrastructure-photograph with description(e.g stp, ugr)

- UGR: Structural work has been completed.
- STP: Capping beam for secant pile work in progress.

3. Construction Status of common area-photograph with description(e.g. - lift well, fire refuge, stair case)

• Lift:

- Tower 1: 11th Floor slab work completed. 12th floor slab work in progress.
- Tower 2: 7th Floor Slab work completed. 8th floor slab work in progress.
- Tower 3: Work up to 1st Floor Completed. 2nd Floor work in progress.
- Tower 4: 4th floor slab completed. 5th floor slab work in progress.
- Podium: Work up to 1st and 2nd Floor Completed.

• Fire Refuge:

- Tower 1: 7th floor level fire refuge platform completed.
- Tower 2: 7th floor level fire refuge platform completed.
- Tower 3: Not reached in that level.
- Tower 4: Not reached in that level.
- Podium: No Scope.

• Staircase:

- Tower 1: Work up to 11th Floor Completed. 12th Floor work in progress.
- Tower 2: Work up to 7th Floor Completed. 8th floor work in progress.
- Tower 3: Work up to 1st Floor Completed. 2nd Floor work in progress.

- Tower 4: Work up to 4th Floor Completed. 5th Floor work in progress.
- Podium: Work up to 1st Floor Completed. 2nd Floor work in progress.