

QUINTESSA

1. **Status and construction of each building with photograph**
2. **Piling Work:** 100% Completed.

- **Sheet Piling:** 100% Completed.
- **Substructure Work:** 68% Completed

2. **Construction status of internal infrastructure-photograph with description(e.g stp,ugr) :**

- **STP :** 46% Completed
- **UGR :** 85% Completed

(Site office, construction road and other necessary initial Infra work for construction done)

--