

1. Status and construction of each building with photograph:

- **Piling Work:** 100% Completed.
- **Substructure Work:** 100% Completed
- **Super-Structure Work:**
 - **1st floor Slab:** 100% Completed.
 - **2nd Floor Slab:** 100% Completed.
 - **3rd Floor Slab:** 15% Completed.

2. Construction status of internal infrastructure-photograph with description(e.g stp,ugr) :

- **STP :** RCC Structural work 100% Completed. Inside waterproofing, Finishing and Electro-mechanical work is pending.
- **UGR :** RCC Structural work 100% Completed. Inside waterproofing work in Progress. Finishing and Electro-mechanical work is pending.

3. Construction Status of common area-photograph with description (e.g-lift well, fire refuge, stair case)

- **Lift wall & Stair Case:** RCC Structural work 100% Completed upto 2nd floor level.