

1. Status and construction of each building with photograph (Piling

Work: 100% Completed.

- **Sheet Piling:** 100% Completed.
- **Substructure Work:** 100% Completed
- **1st floor slab:** 40% completed

2. Construction status of internal infrastructure-photograph with description(e.g stp,ugr) :

- **STP :** RCC Structural work 100% Completed. Inside waterproofing, Finishing and Electro-mechanical work is pending.
- **UGR :** RCC Structural work 100% Completed. Inside waterproofing, Finishing and Electro-mechanical work is pending.

3. Construction Status of common area-photograph with description(e.g-lift well,fire refuge,stair case)

- **Lift wall & Stair Case:** Work in progress upto 1st floor lvl.

(Site office, construction road and other necessary initial Infra work for construction done)

--