

Project Status

CC/ Completed with CC				
Single Block	Brick work of Ground Floor under work - in - progress	Completed without CC		
	Fire System under installation	Under Construction		
	Boundary wall & its foundation work - in - progress	Completed without CC		
	External mandatory open space levelling work is going on	Under Construction		
Construction Status of Internal Infrastructure				
Description				
	Construction Status			
	Under Construction/ Not Started/ Completed without CC/ Completed with CC			
Tiles fitting work from 2nd to 5th floor.	Completed without CC			
Tiles fitting work in Gorund & 1st floor.	Under Construction			
Grill Fitting work in flats window from 1st to 5th floor.	Completed without CC			
Alluminium Window fitting work in Flats Window from 2nd to 5th floor.	Completed without CC			
Door palla fitting work from 2nd to 5th floor.	Completed without CC			
Window granite work from 1st to 5th floor flats	Completed without CC			
Kitchen counter work from 1st to 5th floor flats	Completed without CC			
Roof tiles laying work	Completed without CC			
Construction Status of Common area				
Description				
	Construction Status			
	Under Construction/ Not Started/ Completed without CC/ Completed with CC			
Both Staricase Granite fitting work from 1st to 5th floor.	Completed without CC			
Both Lobbies Granite fitting work from 1st to 5th floor.	Completed without CC			
Lift no. 1 installation work.	Completed without CC			
Civil work in driveway & passage.	Under Construction			