

1. **Status and construction of building with photograph-** mentioning blocks, each floor starting from floor-1 and construction status.

- **Piling** : 100% work completed.
- **Sub Structure** : 100% work completed.
- **Super Structure:**
  - Upto 8<sup>th</sup> floor RCC slab 100% work completed.
  - 9<sup>th</sup> floor RCC work in progress.
- **Internal Wall & Plaster work:**
  - Upto 5<sup>th</sup> Floor Block work in progress.

2. **Construction status of internal infrastructure-photograph with description(e.g stp, ugr)**

- **UGR:** RCC work 100% completed.
- **STP:** Foundation Sub-structure work in progress.

3. **Construction Status of common area-photograph with description(e.g- lift well, fire refuge, stair case)**

- **Stair & Lift well** RCC completed till 8<sup>th</sup> Floor.
- **Fire refuged platform** RCC completed at 7<sup>th</sup> floor.