

ANTARES

1. **Status and construction of building with photograph-** mentioning blocks, each floor starting from floor-1 and construction status.

- **Piling** : 100% work completed.
- **Sub Structure** : 100% work completed.
- **Super Structure:**
 - Ground Floor Slab: RCC 100% work completed.
 - 1st Floor Slab: RCC 100% work completed.
 - 2nd Floor Slab: RCC 100% work completed.
 - 3rd Floor Slab: RCC 100% work completed.
 - 4th Floor Slab: Shuttering work in progress for RCC.
 -

2. **Construction status of internal infrastructure-photograph with description(e.g stp, ugr)**

- **UGR:** RCC work 100% completed & Waterproofing work in progress.

3. **Construction Status of common area-photograph with description(e.g- lift well, fire refuge, stair case)**

- **Stair & Lift well** RCC completed till 3rd Floor.
- **No progress** as of now for other items.