Construction Status of Internal Infrastructure			
Description	Construction Status Under Construction/ Not Started/ Completed without CC/ Completed with CC		Image Serial No.
·			
Duiale Mall Dlasteries	CDOUND		-
Bricks Wall Plastering	GROUND	Completed without CC	1
	FIRST	Completed without CC	2
	SECOND	Completed without CC	3
	THIRD	Completed without CC	4
	FOURTH	Completed without CC	5
	FIFTH	Completed without CC	6
Tiles Work	GROUND	Completed without CC	1
	FIRST	Completed without CC	2
	SECOND	Completed without CC	3
	THIRD	Completed without CC	4
	FOURTH	Completed without CC	5
	FIFTH	Completed without CC	6
Interior Wall Putty and Wall Paint	GROUND	Completed without CC	1
	FIRST	Completed without CC	2
	SECOND	Completed without CC	3
	THIRD	Completed without CC	4
	FOURTH	Completed without CC	5
	FIFTH	Completed without CC	6
Exterior Wall Putty & Paint	GROUND	Completed without CC	7
	FIRST	Completed without CC	7
	SECOND	Completed without CC	7
	THIRD	Completed without CC	7
	FOURTH	Completed without CC	7
	FIFTH	Completed without CC	7