

1.Cluster-06, Unit no. 190 to 203 Pile works is completed.

Sub structure is in progress.

2.Cluster-07, Unit no. 184 to 189

Pile works is completed.

Sub structure works is in progress.

3.Cluster-8, Unit no. 181 TO 183

Pile works is completed.

Sub structure works is in progress.

4.Cluster-9, Unit no. 175 TO 180

Pile works is completed.

Sub structure works is in progress.

5.Cluster-13, Unit no. 131 To 151 & 212

Pile works is completed (147 to 151 & 212).

Pile work is in progress.(131 to 146)

6.Cluster-15, Unit no. 122 to 126

Civil sub structure work is completed. (122 to 126)

Ground floor slab completed. (122 to 126)

1st floor slab is completed.(122 to 126)

Brick Work is in progress.

Roof slab is completed.

Plaster work is in progress.

7.Cluster-23, Unit no. 174

Civil sub structure work is completed.

Ground floor slab is completed.

1st floor slab is completed.

Roof slab is completed.

Brick work is Done.

Electrical work is in progress.

Plaster work is in progress.

Plumbing work is in progress.

Waterproofing work is in progress.

Flooring work is in progress.

8.Cluster-24, Unit no. 158 TO 162

Pile works is completed.

9.Cluster-25, Unit no. 163 TO 167

Pile works is completed.

Sub-structure is in progress.

10.Cluster-29,Unit no. 106 TO 109

Pile works is completed.

Sub structure work is completed.

Ground floor slab completed.

1st floor slab is completed.(106 to 109)

Brick work is in progress.

Roof slab is completed.

Plaster work is in progress.

11.Cluster-32,Unit no. 115 TO 118

Sub structure is completed.

Ground floor slab is completed.

1st floor slab is completed.

Roof slab is completed.

Brick work is in progress.

Electrical work is in progress.

Plaster work is in progress.

12.Cluster-5, Unit no. 204 TO 211

Pile works is completed.

Sub structure is in progress.

13.Cluster-30,Unit no. 110 TO 111

Civil sub structure work completed.

Ground floor slab is completed.

 $1_{\rm st}$ floor slab is completed.

Brick work is started.

Roof slab is completed.

Plaster work is in progress.

14.Cluster-33,Unit no. 119 TO 121

Civil sub structure work is in progress.

Ground floor slab is completed.

1st floor slab is completed.

Brickwork is in progress.

Roof slab is completed.

15.Cluster-31,Unit no. 112 TO 114

Civil sub structure work is in progress.

Ground floor slab is completed.

1st floor slab is completed.

16.Cluster-28,Unit no. 100 TO 105

Pile work is completed.

Sub structure is in progress.

18.Cluster-26,Unit no. 168 TO 173

Pile work is completed.

Sub structure is in progress.

19.Cluster-27,Unit no. 152 TO 157

Pile work is completed.

CLUB:

- Piling Completed.
- Excavation work in completed.
- Raft Completed.
- Retaining Wall completed.
- Ground floor slab completed .
- 1st floor slab is completed.
- Brick work is in progress.
- 2nd floor slab is completed.
- Plaster work is in progress.
- Roof slab is completed.
- POP work is in progress.
- Aluminium work is in progress.
- Fire work is in progress.
- Waterproofing work is in progress.

ROAD

- Flooring work of road is completed at cl-3&4 ,cl-17&19, cl-15&33, cl-20&21, 22&23,31&32,29&30.
- Landscape work is completed.